8gm

Tank has a

Slow Leak. Changed

O-Ring with no Change

Cpl S. Chessher

Lake Co S.O.

352-516-1879