

Jacobs, Jennifer

From: Jayson Levy <motorman190@gmail.com>
Sent: Thursday, February 25, 2016 8:03 AM
To: Jacobs, Jennifer
Subject: Re: Intox 80-1290

OK, thanks, I will mail it later today.

Thanks, Jayson

On Thu, Feb 25, 2016 at 8:02 AM, Jacobs, Jennifer <JenniferJacobs@fdle.state.fl.us> wrote:

Just send it back to me. I will run additional tests. If you need a breath tube, you can just order one and have it sent directly to my office. We will replace it if that is what is needed. I didn't have a problem with temp reg, but it could have been on the end of its life.

From: Jayson Levy [mailto:motorman190@gmail.com]
Sent: Thursday, February 25, 2016 7:59 AM
To: Jacobs, Jennifer
Subject: Re: Intox 80-1290

Should I mail it back to you for shipment to Jay, or can this be done via your office?

Thanks, Jayson

On Thu, Feb 25, 2016 at 7:53 AM, Jacobs, Jennifer <JenniferJacobs@fdle.state.fl.us> wrote:

It could be a loose wire, it could also be just pinched. Try moving around the breath tube and see if they gets it to warm up. If not, you will probably need a new breath tube.

Sent from my Verizon Wireless 4G LTE smartphone

----- Original message -----

From: Jayson Levy <motorman190@gmail.com>

Date: 02/25/2016 7:48 AM (GMT-05:00)

To: "Jacobs, Jennifer" <JenniferJacobs@fdle.state.fl.us>

Subject: Re: Intox 80-1290

it is. Can it possibly be a loose wire?

On Thu, Feb 25, 2016 at 7:47 AM, Jacobs, Jennifer <JenniferJacobs@fdle.state.fl.us> wrote:

Does the breath tube feel cool? Usually a temp fail is because of the breath tube.

Sent from my Verizon Wireless 4G LTE smartphone

----- Original message -----

From: Jayson Levy <motorman190@gmail.com>

Date: 02/25/2016 7:42 AM (GMT-05:00)

To: "Jacobs, Jennifer" <JenniferJacobs@fdle.state.fl.us>

Subject: Re: Intox 80-1290

I tried an inspection last night, and the .05 read .044. I re-tried the inspection after this, and at diagnostic to start the second inspection I got the fail.

I left the unit alone and tried it again this morning, and after warm-up from a standby mode it fails. I have not tried a full power off mode and re-start.

On Thu, Feb 25, 2016 at 7:35 AM, Jacobs, Jennifer <JenniferJacobs@fdle.state.fl.us> wrote:

Are you getting it on initial start up? Are you running a separate diagnostic before running inspection? When is this occurring? Does the breath tube feel cool?

Sent from my Verizon Wireless 4G LTE smartphone

----- Original message -----

From: Jayson Levy <motorman190@gmail.com>

Date: 02/25/2016 7:31 AM (GMT-05:00)

To: "Jacobs, Jennifer" <JenniferJacobs@fdle.state.fl.us>

Subject: Intox 80-1290

Good Morning,

Jennifer I received this unit back yesterday, and I am getting a temp reg fail in the diagnostic check.

Any suggestions?

Jayson