

**Murphy, Patrick**

---

**From:** McKenzie, William <WilliamMcKenzie@flhsmv.gov>  
**Sent:** Saturday, April 01, 2017 1:57 AM  
**To:** Murphy, Patrick  
**Subject:** RE: Deland Intoxilyzer 003410

Well I can not say as that I have firmly identified the issue but after I got low readings again, I swapped simulators a second time. I was then able to get acceptable readings. So short answer is I won't be sending it out to you or anywhere at this time. Hopefully it will be ok going forward. Thanks for the help!

Trooper William S. McKenzie  
Florida Highway Patrol  
133 S. Semoran Blvd, Suite A  
Orlando, Florida 32807  
Office: 407-737-2300  
Fax: 407-737-2373  
[WilliamMcKenzie@flhsmv.gov](mailto:WilliamMcKenzie@flhsmv.gov)  
[www.flhsmv.gov/fhp](http://www.flhsmv.gov/fhp)

**From:** Murphy, Patrick [<mailto:PatrickMurphy@fdle.state.fl.us>]  
**Sent:** Friday, March 31, 2017 7:21 AM  
**To:** McKenzie, William <[WilliamMcKenzie@flhsmv.gov](mailto:WilliamMcKenzie@flhsmv.gov)>  
**Subject:** RE: Deland Intoxilyzer 003410

Should have said, send the tubing if you can spare it.

Pat Murphy  
FDLE ATP

Sent from my Verizon Wireless 4G LTE smartphone

----- Original message -----

**From:** "McKenzie, William" <[WilliamMcKenzie@flhsmv.gov](mailto:WilliamMcKenzie@flhsmv.gov)>  
**Date:** 03/31/2017 4:22 AM (GMT-05:00)  
**To:** "Murphy, Patrick" <[PatrickMurphy@fdle.state.fl.us](mailto:PatrickMurphy@fdle.state.fl.us)>  
**Cc:** "Carpenter, Rodger" <[RodgerCarpenter@flhsmv.gov](mailto:RodgerCarpenter@flhsmv.gov)>  
**Subject:** Deland Intoxilyzer 003410

I am sure you will remember this instrument. This was the one I had shipped to you 2 months ago because it was reading low on the .20 solution. I know it tested fine for you and it did as well for me the next inspection. I tried to do my March inspection and ran into the same issue again. It read .174 and .177. To rule out a simulator issue I swapped it out with the one I was using for the .08 solution. I gave it time to warm up again and it read even lower at .168 and .168. The .08 solution was in range before and after the swaps at .076 and .077 / .079 and .079. So I feel confident it is not a simulator issue. As a side note the .05 solution read within an acceptable range as well during the stability tests.

80-003410

I am taking it out of service because it will not pass the monthly inspection. How do you want to handle this? Ship it back to you again? Please advise, thanks!

My cell 352-255-7197

Trooper William S. McKenzie

Florida Highway Patrol

133 S. Semoran Blvd, Suite A

Orlando, Florida 32807

Office: 407-737-2300

Fax: 407-737-2373

[WilliamMcKenzie@flhsmv.gov](mailto:WilliamMcKenzie@flhsmv.gov)

[www.flhsmv.gov/fhp](http://www.flhsmv.gov/fhp)