

Florida Department of Law Enforcement Alcohol Testing Program

MAR 06 2017

FDLE ✓
Alcohol Testing Program

DEPARTMENT INSPECTION REPORT - INTOXILYZER 8000

Agency: HILLSBOROUGH CO SO
Time of Inspection: 18:03

Date of Inspection: 03/03/2017

Serial Number: 80-000833
Software: 8100.27

BK

Check or Test	YES	NO	Check or Test	YES	NO
Diagnostic Check (Pre-Inspection): OK	Yes		Date and/or Time Adjusted		No
Minimum Sample Volume Check: OK	Yes		Barometric Pressure Sensor Check: OK	Yes	
Alcohol Free Subject Test: 0.000	Yes		Mouth Alcohol Test: Slope Not Met	Yes	
Interferent Detect Test: Interferent Detect	Yes		Diagnostic Check (Post-Inspection): OK	Yes	

Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#:201603D Exp: 03/08/2018	0.08g/210L Test (g/210L) Lot#:201601F Exp: 01/26/2018	0.20g/210L Test (g/210L) Lot#:201604C Exp: 04/05/2018	0.08 g/210L Dry Gas Std Test (g/210L) Lot#:AG626605 Exp: 09/22/2018
0.000	0.050	0.081	0.197	0.081
0.000	0.050	0.081	0.198	0.081
0.000	0.049	0.081	0.198	0.080
0.000	0.050	0.081	0.199	0.080
0.000	0.050	0.081	0.199	0.080
0.000	0.050	0.082	0.198	0.080
0.000	0.050	0.081	0.198	0.081
0.000	0.051	0.080	0.198	0.081
0.000	0.050	0.081	0.198	0.081
0.000	0.050	0.081	0.199	0.081
Standard Deviations	0.0004	0.0004	0.0006	0.0005

Average Standard Deviation of 0.05, 0.08 and 0.20 g/210L Tests: 0.0004 Number of Simulators Used: 5

Remarks:

✓

The above instrument complies () does not comply () with Chapter 11D-8, FAC.

I certify that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.

Daniele M Bell

DANIELLE M BELL

Signature and Printed Name

03/03/2017
Date

RECEIVED

Florida Department of Law Enforcement Alcohol Testing Program

MAR 06 2017
FDLE
Alcohol Testing Program

DEPARTMENT INSPECTION REPORT - INTOXILYZER 8000

Agency: Hillsborough County S.O.
Time of Inspection: 13:30

Date of Inspection: 03/03/2017

Serial Number: 80-000833
Software: 8100.27

Check or Test	YES	NO	Check or Test	YES	NO
Diagnostic Check (Pre-Inspection): OK	X		Date and/or Time Adjusted		X
Minimum Sample Volume Check: OK	X		Barometric Pressure Sensor Check: OK	X	
Alcohol Free Subject Test: 0.000	X		Mouth Alcohol Test: Slope Not Met	X	
Interferent Detect Test: Interferent Detect		X	Diagnostic Check (Post-Inspection): OK		X

Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#: _____ Exp: _____	0.08g/210L Test (g/210L) Lot#: _____ Exp: _____	0.20g/210L Test (g/210L) Lot#: _____ Exp: _____	0.08 g/210L Dry Gas Std Test (g/210L) Lot#: _____ Exp: _____

Standard Deviations				
---------------------	--	--	--	--

Average Standard Deviation of 0.05, 0.08 and 0.20 g/210L Tests: _____ Number of Simulators Used: _____

Remarks: At approximately 13:30 on 03/03/2017, I was in the process of moving a simulator from one location on the bench to another. This required the simulator to pass behind a hanging power cord. As I passed the simulator behind the cord, the simulator bumped the power switch to the entire bench which turned off 4 instruments. 2 instruments were not doing inspections. 2 instruments were in process. Instrument 80-000833 had not started any solutions and was waiting for the alcohol free solution simulator to be available for use. All tests up to this point were in compliance.

Compliance Not Determined. Sequence aborted prior to completion.

The above instrument complies () does not comply () with Chapter 11D-8, FAC.

I certify that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.

Danielle M. Bell

Signature and Printed Name

03/03/2017
Date