

RECEIVED

MAR 06 2017

FDLE

Alcohol Testing Program

Florida Department of Law Enforcement Alcohol Testing Program

DEPARTMENT INSPECTION REPORT - INTOXILYZER 8000

Agency: Pinellas Park PD

Time of Inspection: 13:30

Date of Inspection: 03/03/2017

Serial Number: 80-001042

Software: 8100.27

Check or Test	YES	NO	Check or Test	YES	NO
Diagnostic Check (Pre-Inspection): OK	X		Date and/or Time Adjusted		X
Minimum Sample Volume Check: OK	X		Barometric Pressure Sensor Check: OK	X	
Alcohol Free Subject Test: 0.000	X		Mouth Alcohol Test: Slope Not Met	X	
Interferent Detect Test: Interferent Detect		X	Diagnostic Check (Post-Inspection): OK		X

Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#: Exp:	0.08g/210L Test (g/210L) Lot#: Exp:	0.20g/210L Test (g/210L) Lot#: Exp:	0.08 g/210L Dry Gas Std Test (g/210L) Lot#: Exp:

Standard Deviations			

Average Standard Deviation of 0.05, 0.08 and 0.20 g/210L Tests: _____ Number of Simulators Used: _____

Remarks: At approximately 13:30 on 03/03/2017, I was in the process of moving a simulator from one location on the bench to another. This required the simulator to pass behind a hanging power cord. As I passed the simulator behind the cord, the simulator bumped the power switch to the entire bench which turned off 4 instruments. 2 instruments were not doing inspections. 2 instruments were in process. Instrument 80-001042 was in the middle of running the alcohol free solution when the power was turned off. All values and tests up to this point were in compliance.

[Handwritten initials]

Compliance Not Determined. Sequence aborted prior to completion.

The above instrument complies () does not comply () with Chapter 11D-8, FAC.

I certify that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.

[Handwritten Signature]

Danielle M. Bell

Signature and Printed Name

03/03/2017

Date