

7169
SP

Florida Department of Law Enforcement Alcohol Testing Program

AGENCY INSPECTION REPORT - INTOXILYZER 8000

Agency: FWC
Time of Inspection: UNK

Date of Inspection: 8/24/19

Serial Number: 80-007169
Software:

CHECK OR TEST	YES	NO
Date and/or Time Adjusted		X
Diagnostic Check (Pre-Inspection): OK	X	
Alcohol Free Subject Test: 0.000	X	
Mouth Alcohol Test: Slope Not Met	X	
Interferent Detect Test: Interferent Detect	X	
Diagnostic Check (Post-Inspection): OK	X	

Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#: _____ Exp: _____	0.08g/210L Test (g/210L) Lot#: _____ Exp: _____	0.20g/210L Test (g/210L) Lot#: _____ Exp: _____	0.08 g/210L Dry Gas Std Test (g/210L) Lot#: _____ Exp: _____


Number of Simulators Used: 5

Remarks:

There was an electrical issue with the dry gas interface power cord. Subsequently, there were no readings with any of the three control tests (Dry Gas only). The face of the instrument was illegible. The power surge caused the Dry-Gas cylinder to continuously release dry-gas. I powered the instrument down without the capability to print any paperwork for the inspection test or a communications transfer. An agency inspection could not be successfully completed.

The above instrument complies () does not comply (X) with Chapter 11D-8, FAC.

I certify that I hold a valid Florida Department of Law Enforcement Agency Inspector Permit and that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.



Signature and Printed Name

8/28/19
Date