

DEPARTMENT INSPECTOR FIELD NOTES

Department Inspection: ☐ Registration ☐ Request for Registration Attached ☐ Annual ☐ Inspection After Repair ☐ Other: ☐ Barometric Pressure: ☐ Gauge ☐ Registration Attached ☐ Agency Inspection Notification ☐ Agency Inspection Notification ☐ He following records were audited: ☐ Agency Inspection Reports ☐ He following records were audited: ☐ Agency Inspection Reports ☐ Breath Test Instrument ☐ Repair/Maintenance Records ☐ Instrument Registration ☐ Dry Gas Standard Certificate(s) of ☐ Analysis ☐ Analysis ☐ Cauge	legistration Request for Registration Attached Innual Inspection After Repair	
☐ Registration ☐ Agency Inspection Notification ☐ Agency Inspection Reports ☐ Annual ☐ Agency Contact ☐ Breath Test Instrument Repair/Maintenance Records ☐ Other: ☐ Other ☐ Instrument Registration ☐ Barometric Pressure: ☐ Date of Notification/Contact: ☐ Dry Gas Standard Certificate(s) of Analysis	legistration Request for Registration Attached Innual Inspection After Repair	
Barometric Pressure: Date of Notification/Contact: Analysis		
Agency Inspector: Brad Collito Other: Other:	•	
☐ Instrument Set Up Verified	nstrument Set Up Verified	
Comments:		
Instrument 5249 has been flagging "Interferent Detect" messages at inappropriate times. I have tried	ument 5249 has been flagg	
several times to duplicate at FDLE with no success. To rule out a possible simulator issue, I brought	eral times to duplicate at FD	
FDLE simulators to use in the inspection. Observed the pre-inspection setup and Agency Inspection	E simulators to use in the in	
Instrument/Area: Equipment: Supplies:	ment/Area:	
☑ Clean/Dry ☑ Proper Number of Simulators ☑ Distilled/Deionized Water ☑ Secure ☑ Checked Simulators for Air Leak ☑ Mouth Alcohol Solution ☑ Limited Access ☑ Acetone Stock Solution ☐ Other: ☑ Class A Glassware ☑ Dry Gas Standard ☑ Mouth Pieces	ecure imited Access	
Comments:		
Tested the agency's simulators outside the inspection. The sims had no visible cracks, passed my sea	ed the agency's simulators of	
leak checks, and were recently calibrated within the calendar year. Turned on fan to encourage air flow	checks, and were recently c	
during the Agency Inspection. The AI closed the cap to the acetone bottle right away.	ng the Agency Inspection. T	
Action:	on:	
☐ Instrument Complies with Chapter 11D-8, FAC Comments:	Instrument Complies with Chapter 1	
Instrument Does Not Comply with Chapter 11D-8, FAC Instrument 5249 passed its inspection in my presence with r	Instrument Does Not Comply with Cl	
Remain in Evidentiary Use irregularities or repeated tests. Discussed switching the acetor Return to/Place into Evidentiary Use	_	
Remove from Evidentiary Use and water sims in case there is an undetectable leak causing a Remain Out of Evidentiary Use	Remove from Evidentiary Use	
accumulation effect in the air. Will send to repair if it occurs agai	<u> </u>	
Conduct an Agency Inspection Before Evidentiary Use		
Taylor Gutschow Digitally signed by Taylor Gutschow Date: 2021.10.25 11:19:58 -04'00' 10/25/2021	Date: 202	
Signature of Alcohol Testing Program Staff Member Original – FDLE Copy – Agency	Signature of Alcohol Testing F	