

## Murphy, Patrick

---

**From:** Meresse, Andy <David.Meresse@talgov.com>  
**Sent:** Thursday, May 25, 2017 1:54 PM  
**To:** Murphy, Patrick  
**Subject:** Agency Inspection Issue

Pat,

I just conducted an Agency Inspection (AI) on instrument #2989 registered to the Tallahassee Police Department. Prior to the inspection, I conducted a stability test of the interferent/acetone, and all three alcohol solutions. I had no issues at that time. Once the AI reached the interferent test, the instrument registered the following results on the first attempt:

.000  
\*INT  
\*INT

Per the Agency Inspection Procedures, I re-ran the interferent test and received the following results:

.000  
.000  
\*INT

I ended the AI by noting the instrument was not in compliance. I then conducted a Wet Control Test and again received a .000 result rather than an interferent. The acetone stock solution used in the simulator solution (which was made just prior to testing) is from Lot #2017-A. I have checked the hoses and simulator jar seals which all appear normal. I have also created a completely fresh acetone solution to see if that was the problem (500ml of distilled water and 3ml of acetone solution). Per our conversation, I will conduct multiple stability tests of the new solution and conduct a new AI. Thank you, and I will notify you of the results from this inspection.

**Officer Andy Meresse**  
**Special Operations Division**  
**DUI / Traffic Safety Programs Coordinator**  
**Tallahassee Police Department, FL**  
**(850) 891-4243**

