	☐ Enforcement Electronics
Shipment to repair facility authorized by	y: Paul Frieson on 7/17/2017
Items Returned: Instrument	Supplies Other Please Describe:
Instrument Model: 8000	Serial Number 80-004770
Bill To Address:  SOT PAUL FRIESON  HURLDORT FIELD AIR FORCE BR  521 Cody Ave.  HURLDURT FIELD, FL 32541	2331 Phillips Rd
	TANAINOSC, I C 32308
Reason for Return:  R value below 100, flow	Sensor needs replacement
Please choose one of the follo	IN FOLE TRAINER BOX!
1. I PAUL FRIESON, authorize	e all repairs.
	ze repairs up to \$
Please contact, Name:	
PAUL FRIESON @	Us. Af. mil 919-610-4817
Notes:	

**SHIP TO:** 

CMI, Inc.