

6240  
SP

Good afternoon Shayla,

I am sending you Intoxilyzer 8000 S/N: 80-006240 via UPS, reference the DGST regulator valve appears to be leaking. On 7/6/17 I replaced the DGST regulator valve's O-ring and put a full .08 DGST bottle on the Intoxilyzer (it read 1006 PSI). I then put the instrument in a locked storage cabinet and did not use it for breath testing. On 7/12/17 I checked the instrument and it read below 500 PSI. Based upon our phone conversation on 7/12/17, I concur with your opinion and believe the DGST regulator valve is leaking.

After looking at the Intoxilyzer, if you feel the DGST regulator valve is the issue, please send the Intoxilyzer or DGST regulator valve (whichever you feel is best) to CMI Inc. in Owensboro Kentucky for repair. I have already received approval from my chain of command to have CMI Inc. make the necessary repairs.

If you or anyone at CMI Inc. has any questions reference the above matter, please feel free to contact me.

Jason

Corporal Jason C. Karlecke #6467  
Palm Beach Sheriff's Office  
Agency Inspector/D.U.I. Unit  
2300 North Jog Road  
West Palm Beach, Florida 33411  
Cell. (561) 660-1862  
Email: [KarleckeJ@pbso.org](mailto:KarleckeJ@pbso.org)