

RAM

JENNIFER


I HOPE YOU HAD A GREAT HOLIDAY WITH THE NEW BABY.
I HAD A PROBLEM WITH THIS UNIT (80-000827). DURING THE STABILITY
TEST IT WOULD NOT CLEAR THE CHAMBER KEPT GIVING ME AMB.

I HAD TWO TEST GO PERFECT AND THE THIRD ONE WOULD ONLY GIVE
AMB. THERE WERE NO ENVIRONMENTAL ISSUES IN THE ROOM. I TESTED
THE OTHER UNITS AT THE SAME TIME WITH NO PROBLEM.

I ALSO TURNED THE UNIT OFF AND STARTED OVER IT WENT
THROUGH THE START UP & DIAGNOSTICS WITH NO PROBLEM, TRIED TO
COMPLETE AER BLANK AMB AGAIN. I WAS NOT ABLE TO CONDUCT THE
MONTHLY INSPECTION.

I'M ALSO SENDING SOME OF THE STABILITY RESULTS SLIPS.

THE ~~A~~ AMB SLIPS YOU SEE ARE THE ONES AFTER TURNING IT
OFF AND RESTARTING. IF YOU NEED ANYTHING ELSE
JUST GIVE ME A CALL (352) 843-4215



MARION COUNTY SHERIFF OFFICE.

PGM

MARION COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000 SN 80-000827
12/29/2015
Software: 8100.27

MARION COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000 SN 80-000827
12/29/2015
Software: 8100.27

Test	g/210L	Time
Air Blank	0.000	11:08
Control Test	0.048	11:09
Air Blank	0.000	11:10
Control Test	0.048	11:10
Air Blank	0.000	11:11
Control Test	0.049	11:11
Air Blank	0.000	11:12
Control Test Stats		
Average	0.0483	
Std Dev	0.0006	
Rel Std Dev(%)	1.1945	

Test	g/210L	Time
Air Blank	0.000	11:15
Control Test	0.201	11:16
Air Blank	0.000	11:16
Control Test	0.201	11:17
Air Blank	0.000	11:17
Control Test	0.200	11:18
Air Blank	0.000	11:19
Control Test Stats		
Average	0.2007	
Std Dev	0.0006	
Rel Std Dev(%)	0.2877	

MARION COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000 SN 80-000827
12/29/2015
Software: 8100.27

MARION COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000 SN 80-000827
12/29/2015
Software: 8100.27

Test	g/210L	Time
Air Blank	AMB*	11:28
Air Blank	AMB*	11:28


Test	g/210L	Time
Air Blank	AMB*	11:36
Air Blank	0.000	11:36

*Ambient Fail

*Ambient Fail


Operator's Signature


Operator's Signature


Operator's Signature


Operator's Signature

WBM

INTOXILYZER 8000
Instrument Initialization
11:40 12/29/2015

MARION COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000
12/29/2015
Software: 8100.27

MARION COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000
12/29/2015
Software: 8100.27

Test	g/210L	Time
Air Blank	AMB*	11:37
Air Blank	AMB*	11:38

*Ambient Fail


Operator's Signature

Test	g/210L	Time
Air Blank	AMB*	11:49
Air Blank	AMB*	11:50

*Ambient Fail


Operator's Signature