

Florida Department of Law Enforcement

Alcohol Testing Program

AGENCY INSPECTION REPORT – INTOXILYZER 8000

Agency: BAY COUNTY SO

Serial Number: 80-007478

Time of Inspection:

Date of Inspection: 06/26/2023

Software: 8100.27

CHECK OR TEST	YES	NO
Date and/or Time Adjusted		
Diagnostic Check (Pre-Inspection): OK		
Alcohol Free Subject Test: 0.000		
Mouth Alcohol Test: Slope Not Met		
Interferent Detect Test: Interferent Detect		
Diagnostic Check (Post-Inspection): OK		

Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#: Exp:	0.08g/210L Test (g/210L) Lot#: Exp:	0.20g/210L Test (g/210L) Lot#: Exp:	0.08 g/210L Dry Gas Std Test (g/210L) Lot#: Exp:

Number of Simulators Used: _____

Remarks:

THE JUNE 2023 MONTHLY INSPECTION WAS NOT COMPLETED DUE TO THE INSTRUMENT DISPLAYED THE FOLLOWING ERRORS ON POWER UP.

EEprom Fault
Life data invalid

During diagnostics test after instrument warm up, the following errors were displayed.

Eprom fail and DSP fail

The above instrument complies (X) does not comply () with Chapter 11D-8, FAC.

I certify that I hold a valid Florida Department of Law Enforcement Agency Inspector Permit and that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.

Brian D. Miller
Signature and Printed Name

06/26/2023
Date