

Florida Department of Law Enforcement

Richard L. Swearingen Commissioner **Criminal Justice Professionalism**

Post Office Box 1489
Tallahassee, Florida 32302-1489
(850) 410-8600
www.fdle.state.fl.us

Rick Scott, Governor Pam Bondi, Attorney General Jimmy Patronis, Chief Financial Officer Adam Putnam, Commissioner of Agriculture

Memorandum

To:

Department Inspectors

From:

Brett Kirkland, Program Manager

Date

Monday, August 14, 2017

SUBJECT:

Intoxilyzer 8000 Subject Tests Statistical Data Review Summary - May 2017

The following information is based on the review of the May 2017 subject tests electronic data:

| Breath Test Statistics Total Number of Breath Tests: 2676 | | | Alcohol Concentration Statistics From Breath Samples with No Message Flag | | |
|--|-------|---------|---|------|---------|
| | | | | | |
| | | | Type of Test | | |
| Driving Under the Influence | 2537 | 94.81 % | # of Breath Samples >/=0.08 g/210L | 309 | 91 80 % |
| System Check | 2 | 0.07 % | # of Breath Samples >/=0.15 g/210L | 208 | 32 54 % |
| Administrative | 15 | 0.56 % | Messages (Total Number of Occurrences) | | |
| Boating Under the Influence | 103 | 3.85 % | | | |
| Court Ordered | 7 | 0.26 % | Volume Not Met | 214 | 8.00 % |
| Other | 4 | 0.15 % | Slope Not Met | 7 | 0.26 % |
| Probation/Parole | 7 | 0.26 % | No Sample Provided | 169 | 6.32 % |
| Commercial Motor Vehicle | 0 | 0.00 % | RFI Detect | 103 | 3.85 % |
| 0.02 Enforcement/Zero Tolerance | 1 | 0.04 % | Subject Test Refused | 540 | 20.18 % |
| Breath Sample Statistics | | | Slope Not Level | 4 | 0.15 % |
| and the south and the south of the south and | | | Sequence Aborted | 15 | 0.56 % |
| Total Number of Breath Samples 4853 Average Breath Volume - All Breath Samples 1.767 Liters | | | Interferent Detect | 16 | 0.60 % |
| | 3869 | | Improper Sample | 10 | 0.37 % |
| # of Breath Samples with No Message Flag | | 79.7 % | Range Exceeded | 0 | 0.00 % |
| # of Breath Samples with Message Flag | 984 | 20.3 % | Ambient Fail | 8 | 0.30 % |
| Control Tests During Subject Tests | | | No 0.02 Agreement | 13 | 0.49 % |
| Total # of all Control Tests 5192 | | | Purge Fail | 24 | 0.90 % |
| Average of all Control Test Results 0.079 | | | Control Outside Tolerance | 33 | 1.23 % |
| # Control Tests within Acceptable Range | 5143 | 99.06 % | Temperature Regulation Test | 0 | 0.00 % |
| # Control Tests - Ctl Out Tolerance | 33 | 0.64 % | Analytical Stability Test | 0 | 0.00 % |
| # Control Tests - Interferent Detect | 12 | 0.23 % | EEPROM Checksum Test | 0 | 0.00 % |
| # Control Tests with RFI Detect | 4 | 0.08 % | Voltage/Current Test | 2 | 0.07 % |
| | | | DSP Test | 0 | 0.00 % |
| Air Blanks During Subject Tests | | | Diagnostic Checks During Subject T | ests | |
| Total # of All Air Blanks 15074 | | | Total # of All Diagnostic Checks 5202 | | |
| # of Air Blanks with No Message Flag | 14952 | 99.19 % | # of Diagnostic Checks - OK | 5197 | 99.90 % |
| # of Air Blanks with Message Flag | 122 | 0.81 % | # of Diagnostic Checks - Fail | 5 | 0.10 % |

If you have any questions concerning this information, please feel free to contact me at (850) 617-1290