

Florida Department of Law Enforcement Alcohol Testing Program

AGENCY INSPECTION REPORT - INTOXILYZER 8000

Agency: Jacksonville Sheriff's Office

Serial Number: 80-001279

Time of Inspection:

Date of Inspection: 12/3/2019

Software:

CHECK OR TEST	YES	NO
Date and/or Time Adjusted		
Diagnostic Check (Pre-Inspection): OK		
Alcohol Free Subject Test: 0.000		
Mouth Alcohol Test: Slope Not Met		
Interferent Detect Test: Interferent Detect		
Diagnostic Check (Post-Inspection): OK		

Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#: _____ Exp: _____	0.08g/210L Test (g/210L) Lot#: _____ Exp: _____	0.20g/210L Test (g/210L) Lot#: _____ Exp: _____	0.08 g/210L Dry Gas Std Test (g/210L) Lot#: _____ Exp: _____


Number of Simulators Used: _____

Remarks: On December 3, 2019 at 0945 I was advised that Instrument 80-001279 had failed the RAM portion the Diagnostic Test. At 1000 hours I verified that the Instrument had failed the RAM portion of the Diagnostic Test. I also observed an error message that was being displayed on the Instrument (ERR - 012 Contact CMI). I contacted Department Inspector Patrick Murphy with (FDLE / ATP Tallahassee) decision was made to remove the Instrument from Evidentiary use. The Instrument would need to be inspected and serviced at an approved repair facility. Arrangements were made for the Instrument to be returned to the manufacturer, CMI, Inc. Owensboro KY. for inspection. No Inspection could be performed before removal of Instrument due to the failed Diagnostic Test.

Officer R. D. Lightsey #69016
Agency Inspector
Jacksonville Sheriff's Office

The above instrument complies () does not comply () with Chapter 11D-8, FAC.

I certify that I hold a valid Florida Department of Law Enforcement Agency Inspector Permit and that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.



Robert D Lightsey
Signature and Printed Name

12-3-2019
Date