

6233
SP

Florida Department of Law Enforcement Alcohol Testing Program

AGENCY INSPECTION REPORT - INTOXILYZER 8000

Agency: BREVARD COUNTY S.O.
Time of Inspection: 16:08

Date of Inspection: 05/27/2019

Serial Number: 80-006233
Software: 8100.27

Check or Test	YES	NO
Date and/or Time Adjusted		No
Diagnostic Check (Pre-Inspection): OK	Yes	
Alcohol Free Subject Test: 0.000	Yes	
Mouth Alcohol Test: Slope Not Met	Yes	
Interferent Detect Test: Interferent Detect		No
Diagnostic Check (Post-Inspection): OK		No

Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#: Exp:	0.08g/210L Test (g/210L) Lot#: Exp:	0.20g/210L Test (g/210L) Lot#: Exp:	0.08 g/210L Dry Gas Std Test (g/210L) Lot#: Exp:
0.000				
0.000				
0.000				

Number of Simulators Used: 5

Remarks:


Int Det: . . Non-compliance: .

During the Interferent Detect Test, the Intoxilyzer did not detect the interferent from the simulator. Troubleshooting was conducted. I ensured the simulator container lid was tightened. A follow up test was conducted with the same results observed. The Intoxilyzer was placed out of service due to the instrument not in compliance.


Dep. Robin, G. #3877

The above instrument complies () does not comply (X) with Chapter 11D-8, FAC.

I certify that I hold a valid Florida Department of Law Enforcement Agency Inspector Permit and that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.

 Dep. Robin, G. #3877 GASTON A ROBIN
Signature and Printed Name

05/27/2019
Date