

**From:** [Jesse Burkett](#)  
**To:** [Soto, Israel](#)  
**Subject:** PORT ST JOE PD INTOX 8000 AGENCY INSPECTION  
**Date:** Thursday, March 31, 2022 5:32:08 PM  
**Attachments:** [SKM\\_C36822033114570.pdf](#)  
[SKM\\_C36822033114580.pdf](#)  
[SKM\\_C36822033114581.pdf](#)  
[SKM\\_C36822033114590.pdf](#)  
[SKM\\_C36822033114591.pdf](#)  
[SKM\\_C36822033114592.pdf](#)

---

**CAUTION: This email originated outside of FDLE. Please use caution when opening attachments, clicking links, or responding to this email.**

Officer Burkett 105 PSJPD

Sir,

I have experienced an issue with my first Agency Inspection, due to what appears to be a bad 0.08 solution. A subsequent test was performed after changing out this 0.08 solution Lot # 202007A EXP: 07/21/2022. The second test was in compliance.

Sent from [Mail](#) for Windows