

Florida Department of Law Enforcement Alcohol Testing Program

AGENCY INSPECTION REPORT - INTOXILYZER 8000

Agency: Hialeah Gardens Police Department

Serial Number: 80-001275

Time of Inspection:

Date of Inspection: 10/27/2023

Software: 8100.27

CHECK OR TEST	YES	NO
Date and/or Time Adjusted		No
Diagnostic Check (Pre-Inspection): OK	Yes	
Alcohol Free Subject Test: 0.000	Yes	
Mouth Alcohol Test: Slope Not Met	Yes	
Interferent Detect Test: Interferent Detect	Yes	
Diagnostic Check (Post-Inspection): OK		No


Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#: Exp:	0.08g/210L Test (g/210L) Lot#: Exp:	0.20g/210L Test (g/210L) Lot#: Exp:	0.08 g/210L Dry Gas Std Test (g/210L) Lot#: Exp:
0.000	0.35	N/A	N/A	N/A
0.000	0.35			
0.000				

Number of Simulators Used: 5

Remarks: I was performing the 0.005 test when it went up to 0.35 and then detected interferent. I changed the alcohol solution thinking that it was contaminated and repeated the test. After repeating the test, it gave me the same results as previous. Now the instrument is locked and displays "05 Interferent Detected." on the screen.

The above instrument complies () does not comply (☒) with Chapter 11D-8, FAC.

I certify that I hold a valid Florida Department of Law Enforcement Agency Inspector Permit and that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.



Edwin Huerta 5798

Signature and Printed Name

10/27/2023

Date