

# Florida Department of Law Enforcement

## Alcohol Testing Program

### AGENCY INSPECTION REPORT - INTOXILYZER 8000

Agency: FL Highway Patrol  
 Time of Inspection: 11:40

Date of Inspection: 02-29-2024

Serial Number: 80-006626  
 Software: 8100.27

CHECK OR TEST	YES	NO
Date and/or Time Adjusted		
Diagnostic Check (Pre-Inspection): OK		
Alcohol Free Subject Test: 0.000		
Mouth Alcohol Test: Slope Not Met		
Interferent Detect Test: Interferent Detect		
Diagnostic Check (Post-Inspection): OK		


Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#: Exp:	0.08g/210L Test (g/210L) Lot#: Exp:	0.20g/210L Test (g/210L) Lot#: Exp:	0.08 g/210L Dry Gas Std Test (g/210L) Lot#: Exp:

Number of Simulators Used: —

Remarks: I ATTEMPTED TO CONDUCT THE MONTHLY AGENCY INSPECTION ON INSTRUMENT 80-006626 (TROOP E-MIAMI). THE INSTRUMENT SHOWED A MESSAGE ON THE SCREEN INDICATING "PLEASE WAIT REBUILDING HEADERS." THE INSTRUMENT DID NOT ALLOW ME TO MAKE AN INSPECTION AFTER SEVERAL ATTEMPTS. I SPOKE WITH THE DEPARTMENT INSPECTOR AND HE ADVISED TO SEND THE INSTRUMENT TO GET REPAIR AT CMI.

The\* above instrument complies ( ) does not comply ( ) with Chapter 11D-8, FAC.

I certify that I hold a valid Florida Department of Law Enforcement Agency Inspector Permit and that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.

  
 Signature and Printed Name

Fabian Brandt (0407) Sweetwater P.D.

02-29-2024  
 Date