

Florida Department of Law Enforcement

Richard L. Swearingen

Alcohol Testing Program

P.O. Box 1489

Tallahassee Florida 32302

(850) 617-1290 (850) 921-3787 Fax

www.fdle.state.fl.us/atp

Rick Scott, Govenor Pam Bondi, Attorney General Jeff Atwater, Chief Financial Officer Adam Putnam, Commissioner of Agriculture

Memorandum

Commissioner

To:

Department Inspectors

From:

Brett Kirkland, Program Manager

Date

Thursday, July 21, 2016

SUBJECT:

Intoxilyzer 8000 Subject Tests Statistical Data Review Summary - May 2016

The following information is based on the review of the May 2016 subject tests electronic data:

| Breath Test Statistics Total Number of Breath Tests: 2712 | | | Alcohol Concentration Statistics From Breath Samples with No Message Flag | |
|---|-------|------------|---|--|
| | | | | |
| Type of Test | ···· | y | # of Breath Samples <0.08 g/210L 779 20 % | |
| Driving Under the Influence | 2606 | 96.09 % | # of Breath Samples >/=0.08 g/210L 3111 80 % | |
| System Check | 0 | 0.00 % | # of Breath Samples >/=0.15 g/210L 2047 53 % | |
| Administrative | 17 | 0.63 % | Messages (Total Number of Occurrences) | |
| Boating Under the Influence | 79 | 2.91 % | | |
| Court Ordered | 5 | 0.18 % | Volume Not Met 223 8.22 % | |
| Other | 1 | 0.04 % | Slope Not Met 4 0.15 % | |
| Probation/Parole | 0 | 0.00 % | No Sample Provided 185 6.82 % | |
| Commercial Motor Vehicle | 0 | 0.00 % | RFI Detect 90 3.32 % | |
| 0.02 Enforcement/Zero Tolerance | 4 | 0.15 % | Subject Test Refused 566 20.87 % | |
| Breath Sample Statistics | | | Slope Not Level 6 0.22 % | |
| Total Number of Breath Samples | | 4932 | Sequence Aborted 17 0.63 % | |
| Average Breath Volume - All Breath Samples | | 733 Liters | Interferent Detect 6 0.22 % | |
| # of Breath Samples with No Message Flag | 3890 | | Improper Sample 2 0.07 % | |
| # of Breath Samples with Message Flag | 1042 | 21.1 % | Range Exceeded 0 0.00 % | |
| | 1042 | 21.1 % | Ambient Fail 11 0.41 % | |
| Control Tests During Subject Tests | | | No 0.02 Agreement 19 0.70 % | |
| Total # of all Control Tests | | 5286 | Purge Fail 16 0.59 % | |
| Average of all Control Test Results 0.079 | | | Control Outside Tolerance 35 1.29 % | |
| # Control Tests within Acceptable Range | 5246 | 99.24 % | Temperature Regulation Test 4 0.15 % | |
| # Control Tests - Ctl Out Tolerance | 35 | 0.66 % | Analytical Stability Test 0 0.00 % | |
| # Control Tests - Interferent Detect | 2 | 0.04 % | EEPROM Checksum Test 0 0.00 % | |
| # Control Tests with RFI Detect | 3 | 0.06 % | Voltage/Current Test 6 0.22 % | |
| | | L | DSP Test 0 0.00 % | |
| Air Blanks During Subject Tests | | | Diagnostic Checks During Subject Tests | |
| Total # of All Air Blanks 15304 | | | Total # of All Diagnostic Checks 5290 | |
| # of Air Blanks with No Message Flag | 15212 | 99.40 % | # of Diagnostic Checks - OK 5280 99.81 % | |
| # of Air Blanks with Message Flag | 92 | 0.60 % | # of Diagnostic Checks - Fail 10 0.19 % | |

If you have any questions concerning this information, please feel free to contact me at (850) 617-1290