

48900

Crystal River

# Florida Department of Law Enforcement Alcohol Testing Program

## AGENCY INSPECTION REPORT - INTOXILYZER 8000

Agency: FWC

Serial Number: 80-000900

Time of Inspection: 11:24

Date of Inspection: 11/15/2019

Software: 8100.27

Check or Test	YES	NO
Date and/or Time Adjusted		No
Diagnostic Check (Pre-Inspection): OK	Yes	
Alcohol Free Subject Test: 0.000	Yes	
Mouth Alcohol Test: Slope Not Met	Yes	
Interferent Detect Test: Interferent Detect		No
Diagnostic Check (Post-Inspection): OK		No

Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#:_____ Exp:_____	0.08g/210L Test (g/210L) Lot#:_____ Exp:_____	0.20g/210L Test (g/210L) Lot#:_____ Exp:_____	0.08 g/210L Dry Gas Std Test (g/210L) Lot#:_____ Exp:_____
0.000				
0.000				
0.000				

Number of Simulators Used: 4

Remarks:

Int Det: NEW SIM WASNT WARM, BLOWN FUSE. Non-compliance: INTERFERENT NO DETECTED ALL 3 TEST.

Old simulator blew a fuse in the middle of test. Interferent was not detected on all 3 test. Replaced w/ new electric simulator. New simulator was not completely warm when test was performed. Interferent was not detected on all 3 test. Instrument will be removed from service until next Testing period.

The above instrument complies ( ) does not comply ( X ) with Chapter 11D-8, FAC.

I certify that I hold a valid Florida Department of Law Enforcement Agency Inspector Permit and that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.

N965

RICHARD L. GILMORE

Signature and Printed Name

11/15/2019

Date