

Florida Department of Law Enforcement Alcohol Testing Program

AGENCY INSPECTION REPORT - INTOXILYZER 8000

Agency: HERNANDO COUNTY SO

Time of Inspection: 20:05

Date of Inspection: 10/30/2023

Serial Number: 80-005249

Software: 8100.27

Check or Test	YES	NO
Date and/or Time Adjusted		No
Diagnostic Check (Pre-Inspection): OK	Yes	
Alcohol Free Subject Test: 0.000	Yes	
Mouth Alcohol Test: Slope Not Met	Yes	
Interferent Detect Test: Interferent Detect	Yes	
Diagnostic Check (Post-Inspection): OK		No

Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#:202303J Exp: 03/28/2025	0.08g/210L Test (g/210L) Lot#:202206B Exp: 06/14/2024	0.20g/210L Test (g/210L) Lot#:202206C Exp: 06/15/2024	0.08 g/210L Dry Gas Std Test (g/210L) Lot#:08223080A3 Exp: 06/05/2025
0.000	0.048	0.078	0.198	0.079
0.000	0.048	0.078	0.199	0.078
0.000	0.049	0.078	0.199	0.078

Number of Simulators Used: 5

Remarks:

Non-compliance:DIAGNOSTIC FAILURE.

The above instrument complies () does not comply (X) with Chapter 11D-8, FAC.

I certify that I hold a valid Florida Department of Law Enforcement Agency Inspector Permit and that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.



PATRICK M BAKER

Signature and Printed Name

10/30/2023
Date

HERNANDO COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000 SN 80-005249
10/30/2023
Software: 8100.27

DIAGNOSTICS

Voltage/Current Test	OK
RAM Test	OK
EEPROM Checksum Test	OK
Real Time Clock Test	OK
DSP Test	OK
Analytical Stability Test	OK
Internal Printer Test	OK
Modem Test	OK
Temperature Regulation Test	Fail

Florida Department of Law Enforcement Alcohol Testing Program

AGENCY INSPECTION REPORT - INTOXILYZER 8000

Agency: HERNANDO COUNTY SO
Time of Inspection: 21:29

Date of Inspection: 10/30/2023

Serial Number: 80-005249
Software: 8100.27

Check or Test	YES	NO
Date and/or Time Adjusted		No
Diagnostic Check (Pre-Inspection): OK	Yes	
Alcohol Free Subject Test: 0.000	Yes	
Mouth Alcohol Test: Slope Not Met	Yes	
Interferent Detect Test: Interferent Detect	Yes	
Diagnostic Check (Post-Inspection): OK		No

Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#:202303J Exp: 03/28/2025	0.08g/210L Test (g/210L) Lot#:202206B Exp: 06/14/2024	0.20g/210L Test (g/210L) Lot#:202206C Exp: 06/15/2024	0.08 g/210L Dry Gas Std Test (g/210L) Lot#:08223080A3 Exp: 06/05/2025
0.000	0.048	0.080	0.199	0.079
0.000	0.049	0.080	0.201	0.079
0.000	0.049	0.079	0.201	0.079

Number of Simulators Used: 5

Remarks:

TEMPERATURE REGULATOR FAILURE CAUSING DIAGNOSTIC FAILURENon-compliance: .

The above instrument complies () does not comply (X) with Chapter 11D-8, FAC.

I certify that I hold a valid Florida Department of Law Enforcement Agency Inspector Permit and that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.

Patrick M Baker

PATRICK M BAKER

Signature and Printed Name

10/30/2023
Date

HERNANDO COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000 SN 80-005249
10/30/2023
Software: 8100.27

Test	g/210L	Time
Air Blank	0.000	18:50
Control Test	0.000	18:50
Air Blank	0.000	18:51
Control Test	0.000	18:52
Air Blank	0.000	18:52
Control Test	0.000	18:53
Air Blank	0.000	18:53
Control Test Stats		
Average	0.0000	
Std Dev	0.0000	
Rel Std Dev(%)	0.0000	


Operator's Signature

HERNANDO COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000 SN 80-005249
10/30/2023
Software: 8100.27

Test	g/210L	Time
Air Blank	0.000	18:54
Control Test	INT*	18:55
Air Blank	0.000	18:55
Control Test	INT*	18:56
Air Blank	0.000	18:57
Control Test	INT*	18:57
Air Blank	0.000	18:58
Control Test Stats		
Average	0.0000	
Std Dev	0.0000	
Rel Std Dev(%)	0.0000	

*Interferent Detect


Operator's Signature

HERNANDO COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000 SN 80-005249
10/30/2023
Software: 8100.27

Test	g/210L	Time
Air Blank	0.000	18:59
Control Test	0.048	18:59
Air Blank	0.000	19:00
Control Test	0.049	19:01
Air Blank	0.000	19:01
Control Test	0.049	19:02
Air Blank	0.000	19:02
Control Test Stats		
Average	0.0487	
Std Dev	0.0006	
Rel Std Dev(%)	1.1863	



Operator's Signature

HERNANDO COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000 SN 80-005249
10/30/2023
Software: 8100.27

Test	g/210L	Time
Air Blank	0.000	19:13
Control Test	0.077	19:14
Air Blank	0.000	19:14
Control Test	0.078	19:15
Air Blank	0.000	19:15
Control Test	0.078	19:16
Air Blank	0.000	19:17
Control Test Stats		
Average	0.0777	
Std Dev	0.0006	
Rel Std Dev(%)	0.7434	


Operator's Signature

HERNANDO COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000 SN 80-005249
10/30/2023
Software: 8100.27

Test	g/210L	Time
Air Blank	0.000	19:17
Control Test	0.196	19:18
Air Blank	0.000	19:19
Control Test	0.198	19:19
Air Blank	0.000	19:20
Control Test	0.198	19:21
Air Blank	0.000	19:21
Control Test Stats		
Average	0.1973	
Std Dev	0.0012	
Rel Std Dev(%)	0.5852	


Operator's Signature

Florida Department of Law Enforcement Alcohol Testing Program

AGENCY INSPECTION REPORT - INTOXILYZER 8000

Agency: HERNANDO COUNTY SO
Time of Inspection: 19:57

Date of Inspection: 08/13/2023

Serial Number: 80-005249
Software: 8100.27

Check or Test	YES	NO
Date and/or Time Adjusted		No
Diagnostic Check (Pre-Inspection): OK	Yes	
Alcohol Free Subject Test: 0.000	Yes	
Mouth Alcohol Test: Slope Not Met	Yes	
Interferent Detect Test: Interferent Detect	Yes	
Diagnostic Check (Post-Inspection): OK	Yes	

Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#:202112A Exp: 12/07/2023	0.08g/210L Test (g/210L) Lot#:202206B Exp: 06/14/2024	0.20g/210L Test (g/210L) Lot#:202206C Exp: 06/15/2024	0.08 g/210L Dry Gas Std Test (g/210L) Lot#:08223080A3 Exp: 06/05/2025
0.000	0.048	0.079	0.199	0.078
0.000	0.048	0.079	0.200	0.078
0.000	0.048	0.079	0.200	0.079

Number of Simulators Used: 5

Remarks:

The above instrument complies (☒) does not comply (☐) with Chapter 11D-8, FAC.

I certify that I hold a valid Florida Department of Law Enforcement Agency Inspector Permit and that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.



PATRICK M BAKER



Signature and Printed Name

08/13/2023
Date



INSTRUMENT PROCESSING SHEET

Agency Hernando County Sheriff's OfficeS/N 80-005249Florida Department of
Law EnforcementDate In 6/20/2023DI Completion Date 06-22-2023☒ Ship ☐ P/U ☐ H/D ☐ CMI ☐ EE

Intake	By BS	Quality Checks	By BS	Date <u>6/21/2023</u>	Flow Calibration	By	Date																																								
☒ Annual BS 6/22/2023 ☐ Registration ☒ Return from CMI / EE Visual Inspection: ☒ Case ☒ Handle ☒ Keyboard ☒ Dry Gas Shelf ☒ Feet ☒ Breath Tube ☒ Ports ☒ Screws Tight Other Equipment/ Accessories: ☒ Power cord ☐ Printer Cable ☒ Static Bag ☐ 12V DC Cable Notes: <u>Outer rubber of breath tube frayed.</u>		☒ Breath Tube Screen ☒ Replace External O-Rings ☒ Instrument Set Up Verified ☒ R-Value <u>236</u> ☒ Flow Verification (L/s) Flow Column # <u>ATP-105</u> 32 mm <u>0.156</u> (.139 - .169) 36 mm <u>0.179</u> (.156 - .190) 53 mm <u>0.242</u> (.228 - .278) 103 mm <u>0.519</u> (.447 - .547) ☒ Barometric Pressure Check Gauge ID # <u>28421</u> ☒ Stability Checks			Flow Column # _____ ☐ 5L/min – 17mm ☐ 15L/min – 53mm ☐ 30L/min – 103mm ☐ R-Value _____ ☐ Post Calibration Verification (L/s) Flow Column # _____ 32 mm _____ (.139 - .169) 36 mm _____ (.156 - .190) 53 mm _____ (.228 - .278) 103 mm _____ (.447 - .547)																																										
		<table border="1"><thead><tr><th>Simulator</th><th>Serial #</th><th>Lot #/Exp</th></tr></thead><tbody><tr><td>0.050</td><td>MP5088</td><td>202303K 03/29/2025</td></tr><tr><td>0.080</td><td>MP5089</td><td>202303L 03/29/2025</td></tr><tr><td>0.200</td><td>MP5090</td><td>202304C 04/05/2025</td></tr><tr><td>0.080 DGS</td><td>N/A</td><td>06723080A5 04/05/2025</td></tr></tbody></table>	Simulator	Serial #	Lot #/Exp	0.050	MP5088	202303K 03/29/2025	0.080	MP5089	202303L 03/29/2025	0.200	MP5090	202304C 04/05/2025	0.080 DGS	N/A	06723080A5 04/05/2025					Maintenance By _____ ☐ Battery Replacement ☐ Dry Gas Regulator Replacement ☐ Breath Tube Replacement ☐ Other _____																									
Simulator	Serial #	Lot #/Exp																																													
0.050	MP5088	202303K 03/29/2025																																													
0.080	MP5089	202303L 03/29/2025																																													
0.200	MP5090	202304C 04/05/2025																																													
0.080 DGS	N/A	06723080A5 04/05/2025																																													
Calibration Adjustment By _____		Department Inspection By IS _____																																													
Barometric Pressure Gauge _____ ID # _____		Barometric Pressure ID# <u>28421</u> Gauge 1010 _____ Instrument 1008 _____ Mouth Alcohol Solution Lot # <u>2022-A</u> _____ Acetone Stock Solution Lot # <u>2022-B</u> _____																																													
<table border="1"><thead><tr><th>Simulator</th><th>Serial #</th><th>Lot #</th><th>Expiration</th></tr></thead><tbody><tr><td>0.000</td><td></td><td>N/A</td><td>N/A</td></tr><tr><td>0.040</td><td></td><td></td><td></td></tr><tr><td>0.100</td><td></td><td></td><td></td></tr><tr><td>0.200</td><td></td><td></td><td></td></tr><tr><td>0.300</td><td></td><td></td><td></td></tr><tr><td>0.080 DGS</td><td>N/A</td><td></td><td></td></tr></tbody></table>		Simulator	Serial #	Lot #	Expiration	0.000		N/A	N/A	0.040				0.100				0.200				0.300				0.080 DGS	N/A			<table border="1"><thead><tr><th>Simulator</th><th>Serial Number</th></tr></thead><tbody><tr><td>0.000</td><td>MP6289</td></tr><tr><td>Interferent</td><td>MP6290</td></tr><tr><td>0.050</td><td>MP6291</td></tr><tr><td>0.080</td><td>MP6292</td></tr><tr><td>0.200</td><td>MP6293</td></tr></tbody></table>						Simulator	Serial Number	0.000	MP6289	Interferent	MP6290	0.050	MP6291	0.080	MP6292	0.200	MP6293
Simulator	Serial #	Lot #	Expiration																																												
0.000		N/A	N/A																																												
0.040																																															
0.100																																															
0.200																																															
0.300																																															
0.080 DGS	N/A																																														
Simulator	Serial Number																																														
0.000	MP6289																																														
Interferent	MP6290																																														
0.050	MP6291																																														
0.080	MP6292																																														
0.200	MP6293																																														
☐ Post Calibration Adjustment Stability Checks		Attachments ☒ Form 41 ☐ Post-Stability Checks ☒ Stability Checks ☐ Flow Calibration ☒ Calibration Certificate ☐ Form 40 ☐ Calibration Adjustment ☐ Other _____																																													
<table border="1"><thead><tr><th>Simulator</th><th>Serial #</th><th>Lot #</th><th>Expiration</th></tr></thead><tbody><tr><td>0.050</td><td></td><td></td><td></td></tr><tr><td>0.080</td><td></td><td></td><td></td></tr><tr><td>0.200</td><td></td><td></td><td></td></tr><tr><td>0.080 DGS</td><td>N/A</td><td></td><td></td></tr></tbody></table>		Simulator	Serial #	Lot #	Expiration	0.050				0.080				0.200				0.080 DGS	N/A			☒ Instrument Complies with Chapter 11D-8, FAC ☐ Instrument Does Not Comply with Chapter 11D-8, FAC ☒ Return to/Place into Evidentiary Use ☐ Remain Out of Evidentiary Use ☒ Conduct an Agency Inspection Before Evidentiary Use																									
Simulator	Serial #	Lot #	Expiration																																												
0.050																																															
0.080																																															
0.200																																															
0.080 DGS	N/A																																														
Notes/Suggested Service: <u>Tech review: Added check to Annual Intake for instrument's annual inspection. BS 6/22/2023</u>		Taylor Gutschow Digitally signed by Taylor Gutschow Date: 2023.06.22 15:52:46 -0400		Phil Nicodemo Digitally signed by Phil Nicodemo Date: 2023.06.23 10:57:01 -0400																																											
		Tech Review / Date		Admin Review / Date																																											

Florida Department of Law Enforcement Alcohol Testing Program

DEPARTMENT INSPECTION REPORT - INTOXILYZER 8000

Agency: HERNANDO COUNTY SO
Time of Inspection: 12:06

Date of Inspection: 06/22/2023

Serial Number: 80-005249
Software: 8100.27

Check or Test	YES	NO	Check or Test	YES	NO
Diagnostic Check (Pre-Inspection): OK	Yes		Date and/or Time Adjusted		No
Minimum Sample Volume Check: OK	Yes		Barometric Pressure Sensor Check: OK	Yes	
Alcohol Free Subject Test: 0.000	Yes		Mouth Alcohol Test: Slope Not Met	Yes	
Interferent Detect Test: Interferent Detect	Yes		Diagnostic Check (Post-Inspection): OK	Yes	

Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#: 202201C Exp: 01/11/2024	0.08g/210L Test (g/210L) Lot#: 202303L Exp: 03/29/2025	0.20g/210L Test (g/210L) Lot#: 202201E Exp: 01/18/2024	0.08 g/210L Dry Gas Std Test (g/210L) Lot#: AG229803 Exp: 10/25/2024
0.000	0.049	0.080	0.201	0.077
0.000	0.048	0.080	0.201	0.077
0.000	0.048	0.081	0.202	0.077
0.000	0.049	0.081	0.202	0.076
0.000	0.049	0.081	0.201	0.076
0.000	0.049	0.081	0.201	0.077
0.000	0.049	0.081	0.201	0.077
0.000	0.049	0.081	0.202	0.077
0.000	0.049	0.081	0.202	0.077
0.000	0.050	0.081	0.202	0.077

Standard Deviations	0.0005	0.0004	0.0005	0.0004
---------------------	--------	--------	--------	--------

Average Standard Deviation of 0.05, 0.08 and 0.20 g/210L Tests: 0.0004 Number of Simulators Used: 5

Remarks:

The above instrument complies (☒) does not comply (☐) with Chapter 11D-8, FAC.

I certify that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.

Israel Soto

ISRAEL SOTO

Signature and Printed Name

06/22/2023
Date

Stability Checks

HERNANDO COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000 SN 80-005249
06/21/2023
Software: 8100.27

Test	g/210L	Time
Air Blank	0.000	14:06
Control Test	0.050	14:07
Air Blank	0.000	14:08
Control Test	0.049	14:08
Air Blank	0.000	14:09
Control Test	0.049	14:09
Air Blank	0.000	14:10
Control Test Stats		
Average	0.0493	
Std Dev	0.0006	
Rel Std Dev(%)	1.1703	


HERNANDO COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000 SN 80-005249
06/21/2023
Software: 8100.27

Test	g/210L	Time
Air Blank	0.000	14:14
Control Test	0.079	14:15
Air Blank	0.000	14:15
Control Test	0.079	14:16
Air Blank	0.000	14:17
Control Test	0.079	14:17
Air Blank	0.000	14:18
Control Test Stats		
Average	0.0790	
Std Dev	0.0000	
Rel Std Dev(%)	0.0000	

HERNANDO COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000 SN 80-005249
06/21/2023
Software: 8100.27

Test	g/210L	Time
Air Blank	0.000	14:21
Control Test	0.200	14:22
Air Blank	0.000	14:22
Control Test	0.200	14:23
Air Blank	0.000	14:23
Control Test	0.200	14:24
Air Blank	0.000	14:25
Control Test Stats		
Average	0.2000	
Std Dev	0.0000	
Rel Std Dev(%)	0.0000	


Operator's Signature


Operator's Signature


Operator's Signature

HERNANDO COUNTY SO
Intoxilyzer - Alcohol Analyzer
Model 8000 SN 80-005249
06/21/2023
Software: 8100.27

Test	g/210L	Time
Air Blank	0.000	14:28
Control Test	0.078	14:28
Air Blank	0.000	14:29
Control Test	0.078	14:29
Air Blank	0.000	14:30
Control Test	0.078	14:30
Air Blank	0.000	14:30
Control Test Stats		
Average	0.0780	
Std Dev	0.0000	
Rel Std Dev(%)	0.0000	

DGS


Operator's Signature



Calibration Certificate

Florida Department of Law Enforcement
Alcohol Testing Program
2331 Phillips Road.
Suite B1032
Tallahassee, FL 32308

This is to certify the calibration of Intoxilyzer 8000 serial number 80-005249, manufactured by CMI, Inc. was calibrated in accordance with FDLE/ATP Form 36 - Department Inspection Procedures - Intoxilyzer 8000.

Serial Number:	80-005249	UNCERTAINTY* $\pm$	
Owning Agency:	HERNANDO COUNTY SO	0.050 g/ 210 L	0.004
Calibration Date:	06/22/2023	0.080 g/ 210 L	0.004
Calibration Time:	12:06	0.200 g/ 210 L	0.007
		0.080 g/ 210 L Dry Gas Control	0.005

All results are reported in g/ 210 L.

Bias is limited by calibration acceptance criteria. All calibration results must be within $\pm$ 0.005 or 5%, whichever is greater, of the target alcohol concentration.

*Uncertainty is based on fleet-wide data and is expressed to a 99.73% level of confidence (k=3).

The instrument results before and after any adjustment are found in the associated pre and post stability checks.

TRACEABILITY INFORMATION

This instrument was calibrated using solutions prepared by Alcohol Countermeasure Systems, Inc. (ACS). ACS prepared and certified these CRMs in accordance with ISO 17034 and ISO/ IEC 17025 Standards.

Simulator temperatures are traceable to NIST. Simulator temperatures are checked with NIST traceable digital thermometers calibrated by Precision Metrology in accordance with ISO/ IEC 17025 standards.

Dry gas control measurements are traceable to NIST through the use of CRMs supplied by an accredited CRM supplier. The supplier of dry gas standard controls prepared and certified the CRMs in accordance with ISO Guide 34 and ISO/ IEC 17025 standards.

This document shall not be reproduced except in full, without written approval of the Florida Department of Law Enforcement Alcohol Testing Program.

Digitally signed by Israel

Soto

Date: 2023.06.22 15:17:23
-04'00'

Israel Soto

Date

ISRAEL SOTO,

Department Inspector

FDLE/ATP Form 69 March 2022
Issuing Authority: Alcohol Testing Program

Service • Integrity • Respect • Quality

Return Material Authorization

Ship to: ☒ CMI, Inc.

☐ Enforcement Electronics

Shipment to repair facility authorized by: Brad Collito on 02-17-2023

Items Returned: Instrument ☒ Supplies ☐ Other ☐ Describe: _____

Instrument Model: Intoxilyzer 8000 Serial Number: 80-005249

Bill To Address:

Hernando County Sheriff's Office

Florida

Ship to Address:

Florida Department of Law Enforcement

Alcohol Testing Program

813 B Lake Bradford Road

Tallahassee, FL 32304

Reason for Return:

Instrument was producing Interferent Detect with DI water and received Ambient Fails
in the field. Instrument then started having DSP Fail during the initial Diagnostic Check.

Please choose one of the following options:

- ☐ 1. I _____, authorize all repairs.
- ☐ 2. I _____, authorize repairs up to \$_____.
- ☒ 3. I require an estimate **BEFORE** any repairs will be authorized and/ or conducted.

Please contact: Name: Brad Collito

Phone #: 352-544-2334 Email: bcollito@hernandosheriff.org

ATP Contact Name: Israel Soto ATP Email: israelsoto@fdle.state.fl.us

Certificate of Calibration

This is to certify the calibration of **Intoxilyzer**® serial number 8005245, manufactured by CMI Inc., a subsidiary of MPD, Inc. of Owensboro, Kentucky, was tested and found to conform to the National Highway Traffic Safety Administration (NHTSA) Standard for Devices to Measure Breath Alcohol (Federal Register, Vol.58 No.179, pp 48705-48710, Sept. 17, 1993) for accuracy and precision. Reference materials are traceable through the National Institute of Standards and Technology (NIST) to the International System of Units (SI).

Date June 12, 2023

Signed

Brandy Blair

Technician



316 East 9th Street
Owensboro, KY 42303
USA

Part No 650517 Rev A

**SERVICE WORK ORDER**

DATE: 2/22/2023

316 E 9th Street / Owensboro KY 42303 / USA
Phone: 866-835-0690 Fax: 270-685-6268

407603

Bill To:Hernando County Sheriff's Office
PO Box 10070
Brooksville, FL 34603-0070
USA
Customer #: 346090
Phone: 352-797-3424**Ship To:**FDLE- ALCOHOL TESTING
813- B LAKE RD
TALLAHASSEE FL 32304
USA**MODEL #:** 002480FL**Serial Number:** 80-005249**BILL CODE:** Out of Warranty**EXTRA PARTS RCVD:**

BH, KB, BATTERY, GAS SHELF

DESCRIPTION OF PROBLEM

INSTRUMENT WAS PRODUCING INTERFERENT DETECT WITH DI WATER AND RECEIVED AMBIENT FAILS IN THE FIELD. INSTRUMENT THEN STARTED HAVING DSP FAIL DURING THE INITIAL DIAGNOSTIC CHECK.

WORK PERFORMED:

Replaced parts listed; Cal adjust/ Cal finale; Software 8100.27; "Updates Completed"; "Nuke Flash"; "memory cleared".

PARTS USED

Seq. No.	Part	Description	Quantity
100	650517	CERTIFICATE OF CALIBRATION	2.00 EA
110	441169	COVER DUST, 5/8in x 1/2in	1.00 EA
120	470145	CAP, PLASTIC, .25IDx.50LG, RED	3.00 EA
130	470154	CAP, PLSTC, .406IDx.438-.562, RED	1.00 EA
140	470218	SEAL, TAMPER EVIDENT, SERVICE	1.00 EA
150	020982	SOURCE ASSY	1.00 EA
160	021357	SOLENOID ASSY, I8000	1.00 EA
170	690040	BATTERY, 3VOLT, LITHIUM, CR2032	1.00 EA

LABOR / TESTING

Misc Code	Description	Hours
LABR	Service Repair Labor	
LCAL	Service - Calibration Adjust	0.50
LFT	Service - Cal / Final Test	1.00

Technician Name: Levi Ray

SRV4076030001



DATE: 2/22/2023



316 E 9th Street / Owensboro KY 42303 / USA
Phone: 866-835-0690 Fax: 270-685-6268

SERVICE WORK ORDER

407603

Thank you for choosing CMI, Inc.

We wouldn't be here if it weren't for you...
And we know it.

Hopefully, our commitment to giving you a quality product was a key factor in your decision to purchase your Intoxilyzer. This is not where the quality ends; however, it is just where it begins. We pride ourselves on continuing to provide quality service and support through the life of this Intoxilyzer and all of your future Intoxilyzer purchases.

The ongoing quality service and support CMI provides can be accessed by dialing one number:

1-866-835-0690

If you have question about billing, shipping or other CMI products, Dialing 1-866-835-0690 can put you in touch with CMI Customer Service.

Dialing 1-866-835-0690 can also get answers to questions about setting up your instrument, installing software or servicing your instrument - just ask for one of our qualified service technicians.

CMI is an employee owned company and each one of us wants you to be a satisfied customer. We stand behind every one of our products. Our quality manufacturing, service and support is what sets us apart from the rest. Call us and you'll experience the difference.

Technician Name: Levi Ray

SRV4076030001



SCTicket: SDH-PROD:Ver1.7 (2020-01-16)

Page: 2 of 3

DATE: 2/22/2023



316 E 9th Street / Owensboro KY 42303 / USA
Phone: 866-835-0690 Fax: 270-685-6268

SERVICE WORK ORDER

407603

Statement of Warranty

Repair Product Warranty

Out of warranty product repairs are warranted for 90 days from the date of repair. This includes labor and those parts, which are replaced. If additional repair is required within the 90 day period, there will be a charge for any parts that were not originally replaced. Repairs made during the 90 day period that are unrelated to the original repair are not covered under the warranty.

There are no warranties expressed or implied, either oral or written, other than those contained in this warranty. In no event shall CMI be liable for any loss of profits or any indirect or consequential damages arising out of any such defect in material or workmanship.



Breath Alcohol Testing Is Our Business

316 East 9th Street
Owensboro, KY 42303
1-866-835-0690
www.alcoholtest.com

Technician Name: Levi Ray

SCTicket: SDH-PROD:Ver1.7 (2020-01-16)

SRV4076030001



Page: 3 of 3

Florida Department of Law Enforcement Alcohol Testing Program

AGENCY INSPECTION REPORT - INTOXILYZER 8000

Agency: HERNANDO COUNTY SO
Time of Inspection: 11:20

Date of Inspection: 02/11/2023

Serial Number: 80-005249
Software: 8100.27

Check or Test	YES	NO
Date and/or Time Adjusted		No
Diagnostic Check (Pre-Inspection): OK	Yes	
Alcohol Free Subject Test: 0.000	Yes	
Mouth Alcohol Test: Slope Not Met	Yes	
Interferent Detect Test: Interferent Detect		No
Diagnostic Check (Post-Inspection): OK		No

Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#:_____ Exp:_____	0.08g/210L Test (g/210L) Lot#:_____ Exp:_____	0.20g/210L Test (g/210L) Lot#:_____ Exp:_____	0.08 g/210L Dry Gas Std Test (g/210L) Lot#:_____ Exp:_____
INT / 0.000				
/ 0.000				

Number of Simulators Used: 5

Remarks:

00: Interferent Detect, Ambient Fail. Non-compliance:INT AN AMB FAILURE.

02/11/23

The above instrument complies (*X*) does not comply (~~X~~) with Chapter 11D-8, FAC.

I certify that I hold a valid Florida Department of Law Enforcement Agency Inspector Permit and that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.

BC 1193

BRAD R COLLITO

Signature and Printed Name

02/11/2023
Date

Florida Department of Law Enforcement Alcohol Testing Program

AGENCY INSPECTION REPORT - INTOXILYZER 8000

Agency: HERNANDO COUNTY SO
Time of Inspection: 11:34

Date of Inspection: 02/11/2023

Serial Number: 80-005249
Software: 8100.27

Check or Test	YES	NO
Date and/or Time Adjusted		No
Diagnostic Check (Pre-Inspection): OK	Yes	
Alcohol Free Subject Test: 0.000		No
Mouth Alcohol Test: Slope Not Met		No
Interferent Detect Test: Interferent Detect		No
Diagnostic Check (Post-Inspection): OK		No

Alcohol Free Test (g/210L)	0.05g/210L Test (g/210L) Lot#: Exp:	0.08g/210L Test (g/210L) Lot#: Exp:	0.20g/210L Test (g/210L) Lot#: Exp:	0.08 g/210L Dry Gas Std Test (g/210L) Lot#: Exp:
INT / 0.000				
/ 0.000				

Number of Simulators Used: 5

Remarks:

00: Interferent Detect, Ambient Fail. Non-compliance: INT AN AMB FAILURE. A F / M A: Ambient Fail. No n-compliance: . *02/11/23*

The above instrument complies (*3C* ☒) does not comply (*AL* ☐) with Chapter 11D-8, FAC.

I certify that I hold a valid Florida Department of Law Enforcement Agency Inspector Permit and that I performed this inspection in accordance with the provisions of Chapter 11D-8, FAC.

BC 1193

BRAD R COLLITO

Signature and Printed Name

02/11/2023
Date