

Stability Checks

0.05g/210L	0.08g/210L	0.20g/210L	DGS 0.08g/210L
0.047 to 0.053	0.077 to 0.083	0.194 to 0.206	0.077 to 0.083 ≤0.003 of Wet
<p>FL Highway Patrol Proximeter - Alcohol Analyzer Model: 8100 10/04/2023 Software: 8100.27</p> <p>Test Time</p> <p>Air Blank 9/21/0L 10:11 Control Test 10:11 Air Blank 10:11 Ambient Fail 10:11</p> <p>Operator's Signature</p>	<p>FL Highway Patrol Proximeter - Alcohol Analyzer Model: 8100 10/04/2023 Software: 8100.27</p> <p>Test Time</p> <p>Air Blank 9/21/0L 10:14 Control Test 10:15 Air Blank 10:15 Ambient Fail 10:16</p> <p>Operator's Signature</p>	<p>FL Highway Patrol Proximeter - Alcohol Analyzer Model: 8100 10/04/2023 Software: 8100.27</p> <p>Test Time</p> <p>Air Blank 9/21/0L 10:19 Control Test 10:19 Air Blank 10:19 Ambient Fail 10:19</p> <p>Operator's Signature</p>	<p>FL Highway Patrol Proximeter - Alcohol Analyzer Model: 8100 10/04/2023 Software: 8100.27</p> <p>Test Time</p> <p>Air Blank 9/21/0L 10:21 Control Test 10:21 Air Blank 10:22 Ambient Fail 10:22</p> <p>Operator's Signature</p>

Return Material Authorization

Ship to: ☒ CMI, Inc.

☐ Enforcement Electronics

Shipment to repair facility authorized by: Yosniel Lorenzo on 10/04/2023

Items Returned: Instrument ☒ Supplies ☐ Other ☐ Describe: _____

Instrument Model: Intoxilyzer 8000 Serial Number: 80-001122

Bill To Address:

Sweetwater Police Department

Attn: Yosniel Lorenzo

Ship to Address:

Florida Dept. of Law Enforcement

Attn: Alcohol Testing Program

4700 Terminal Drive, Suite 1

Fort Myers, FL 33907

Reason for Return:

Instrument is detecting Interferents and Ambient Fails on all samples.

Please choose one of the following options:

☐ 1. I _____, authorize all repairs.

☐ 2. I _____, authorize repairs up to \$_____.

☒ 3. I require an estimate **BEFORE** any repairs will be authorized and/ or conducted.

Please contact: Name: Yosniel Lorenzo

Phone #: 1-786-603-4165

Email: ylorenzo@cityofsweetwater.fl.gov

ATP Contact Name: Taylor Gutschow

ATP Email: TaylorGutschow@fdle.state.fl.us